Map ID MAP FINDINGS

Direction Distance

EDR ID Number Elevation Database(s) EPA ID Number Site

KS1470 PS 195 BROOKLYN NY LTANKS S102151008 131 IRWIN ST **NY Spills** East N/A BROOKLYN, NY

CLOSED-LACKOF RECENT INFO

1.860 mi.

> 1

9820 ft. Site 1 of 2 in cluster KS

Relative: LTANKS: Higher Name:

Address: 131 IRWIN ST Actual: City, State, Zip: BROOKLYN, NY 2 ft.

Spill Number/Closed Date: 9314709 / 2003-03-10 Facility ID: 9314709

Site ID: 163110 Spill Date: 1994-03-15 Spill Cause: Tank Test Failure

Spill Source: Institutional, Educational, Gov., Other

Spill Class: C3

Cleanup Ceased: Not reported SWIS: 2401

Investigator: ADMIN. CLOSED Referred To: Not reported Reported to Dept: 1994-03-15 CID: Not reported Water Affected: Not reported Spill Notifier: Other Last Inspection: Not reported Recommended Penalty: False Meets Standard: False **UST Involvement:** False Remediation Phase: Date Entered In Computer: 1994-03-21

Spill Record Last Update: 2003-03-10 Spiller Name: Not reported Spiller Company: Not reported Spiller Address: Not reported Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 137568

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead DEC Field was

ADMIN.CLOSED 10/10/95: This Is Additional Information About Material Spilled From The Translation Of The Old Spill File: Ttf.03/10/2003-

Closed Due To The Nature / Extent Of The Spill Report."

"COULD NOT HOLD PRODUCT LEVEL - WILL TEST OTHER TANK ON THURSDAY. NO Remarks:

ACTION YET - NO OTHER INFORMATION. CLOSED DUE TO LACK OF ANY RECENT

INFO-DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID: 9314709 Spill Number: 9314709 Spill Tank Test: 1542498 Site ID: 163110 Tank Number: Not reported

Tank Size: Material: 0001 EPA UST: Not reported UST: Not reported Cause: Not reported Map ID MAP FINDINGS

Direction Distance Elevation

EDR ID Number Database(s) EPA ID Number Site

Source: Not reported Test Method: Test Method 2: Unknown Leak Rate: .00

Gross Fail: Not reported Modified By: Spills Last Modified Date: Not reported

All Materials:

163110 Site ID: Operable Unit ID: 996638 Operable Unit: 01 Material ID: 386496 0001A Material Code: Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: -1.00 Units: L Recovered: .00

Not reported Oxygenate:

SPILLS:

PS 195 BROOKLYN Name: Address: 131 IRWIN ST City.State.Zip: BROOKLYN, NY Spill Number/Closed Date: 9509112 / 1995-11-16

Facility ID: 9509112 Facility Type: ER DER Facility ID: 137568 163111 Site ID: DEC Region: 2 Spill Cause: Unknown Spill Class: ВЗ SWIS: 2401 Spill Date: 1995-10-24 Investigator: **MCTIBBE**

Referred To: Not reported Reported to Dept: 1995-10-24 CID: 270 Water Affected: Not reported

Spill Source: Commercial/Industrial Spill Notifier: Responsible Party Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False

Remediation Phase: Date Entered In Computer: 1995-10-24 Spill Record Last Update: 1995-11-16 Spiller Name: JIM DENNING Spiller Company: PS 195 BROOKLYN Spiller Address: 131 IRWIN ST

0

Spiller Company: 001

JIM DENNING Contact Name:

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was Map ID MAP FINDINGS
Direction

Distance Elevation Site

Database(s) EP/

EDR ID Number EPA ID Number

TIBBE spill closed on 11/16/95, refered to spill # 9314709, Koon Tang

is handling it."

Remarks: "SOME SOIL SAMPLES CAME BACK POSITIVE FROM AROUND TANKS"

All Materials:

Site ID: 163111 Operable Unit ID: 1019685 Operable Unit: 01 Material ID: 553730 Material Code: 0002A Material Name: #4 fuel oil Not reported Case No.: Material FA: Petroleum Quantity: .00 Units: G Recovered: .00

Oxygenate: Not reported